

# MONTHLY PROGRESS REPORT

**PRIME RESIDENCIES EDMONTON ROAD**  
No 01, Edmonton Road, Colombo 05

**JUNE 2019**



## ***EDMONTON 02***

COLOMBO 05

## 1. PROJECT DETAILS

<b>Project Architect</b> : Anil Kumarage, Chartered Architect	<b>Piling Contractor</b> : Sierra Piling (Pvt) Ltd
<b>Structural Engineer</b> : Eng. Laksiri Cooray	<b>Main Contractor</b> : SMI Engineering (Pvt) Ltd
<b>MEP Engineer</b> : Eng. K. P. A. Weerasinghe	<b>Project Commenced Date</b> : 22/03/2018

## 2. CURRENT STATUS OF THE PROJECT

Progress Up to this Month (%)											
Description	Base mnt	G. Flr	1 <sup>st</sup> Flr	2 <sup>nd</sup> Flr	3 <sup>rd</sup> Flr	4 <sup>th</sup> Flr	5 <sup>th</sup> Flr	6 <sup>th</sup> Flr	7 <sup>th</sup> Flr	8 <sup>th</sup> Flr	Roof
<b>Sub Structure</b>	100										
<b>Superstructure</b>	100	100	100	100	100	100	100	100	50		
<b>Masonry Work</b>											
Brick Work	-	-	100	100	100	90	5				
Internal Plastering	100		80	100	70						
<b>Painting Work</b>											
Wall putty	80		50	30							
<b>Electrical</b>											
Conduit & wiring	50	50	50	90	50						

3. PROJECT PICTURES



Figure 3.1- Front view from base line



Figure 3.2 – Side view



Figure 3.3- 7<sup>th</sup> floor slab formwork



Figure 3.4- 6<sup>th</sup> floor column casting



Figure 3.5-3<sup>rd</sup> floor Electrical works



Figure 3.6-4<sup>th</sup> floor Brickworks



Figure 3.7- 2<sup>nd</sup> floor electrical works



Figure 3.8 – 3<sup>rd</sup> floor soffit wiring



Figure 3.9- 3<sup>rd</sup> floor plastering



Figure 3.10-staircase 4<sup>th</sup> to 5<sup>th</sup>.



Figure 3.11- Basement painting



Figure 3.12-5<sup>th</sup> floor Brick works