

# **MONTHLY PROGRESS REPORT**

## **PRIME RESIDENCIES KIRIBATHGODA AUGUST/ 2019**



**K100**

## MONTHLY PROGRESS REPORT- AUGUST 2019

## PROJECT DETAILS

<b>Project Architect : Mr.Anil Kumarage, Chartered Architect</b>	<b>Contractor : INT.ARC construction(Lot 1&amp;2) / PRIME (Lot3&amp;4) &amp; JSM construction(Lot 5)</b>
<b>Structural Engineer : Eng. Laksiri Cooray</b>	<b>Project Commenced Date – 2016/02/15</b>
<b>MEP Engineer : Eng. K. P. A. Weerasinghe</b>	

**CURRENT STATUS OF THE PROJECT - PROJECT COMPLETED****LOT 01**

Super structure	100%
Brick work	100%
Internal plastering	100%
External plastering	100%
Painting work	100%
Ex. painting	100%
Electrical work	100%
Internal Plumbing work	100%
External plumbing	100%
Fixing door	100%
Roof work	100%
Bath room water proofing work	100%
Bathroom tiling	100%
Floor tiling	100%
Lobby tiling	100%
staircase	100%
Lift wall tiling	100%
Terrace tiling	100%
Aluminum work	100%
Lift work – mechanical & electrical installation	100%
Generator work	100%
Terrace heat insulation & water proofing work	100%

## LOT 02

Super structure	100%
Brick work	100%
Internal plastering	100%
External plastering	100%
Painting work	100%
Ex. painting	100%
Electrical work –House wiring	100%
Fixing light fittings	100%
Internal Plumbing work	100%
External plumbing work	100%
Water proofing work	100%
Fixing door frames	100%
Fixing main and plywood doors	100%
Door painting work	100%
Lift work – mechanical installation	100%
Electrical installation	100%
Bathroom tiling	100%
House tiling	100%
Aluminum work	100%
Terrace heat insulation & water proofing work	100%
Fixing bathroom fittings	100%
Generator work	100%

## LOT 03

Super structure	100%
Brick work	100%
Internal plastering	100%
External plastering	100%
Painting work	100%
Electrical work – House wiring	100%
Internal Plumbing work	100%
External plumbing	100%
Fixing Bathroom fitting	100%
Water proofing	100%
Aluminum work	100%
Fixing door frames	100%
Fixing main doors & ply wood doors	100%
Painting doors	100%
house tiling	100%
Bathroom tiling	100%
Roof work - structure	100%
Roof covering	100%
Ceiling work	100%
Lift work - mechanical	100%
-electrical work	100%
Terrace heat insulation & water proofing work	100%

#### LOT 04

Super structure	100%
Brick work	100%
Internal plastering	100%
External plastering	100%
Painting work	100%
External painting	100%
Electrical work – House wiring	100%
Internal Plumbing work	100%
Fixing bathroom fittings	100%
External plumbing work	100%
Fixing door frames	100%
Fixing door sashes	100%
Painting door sashes and frame	100%
Roof work - structure	100%
Roof - covering	100%
Bath room water proofing work	100%
Lift work – mechanical installation	100%
- Electrical installation	100%
Floor tiling work	100%
Bathroom tiling	100%
Aluminum work	100%
Ceiling work	100%
Terrace heat insulation & water proofing work	100%

#### LOT 05

Super structure	100%
Brick work	100%
Internal plastering	100%
External plastering	100%
Painting work	100%
Electrical work – House wiring	100%
Internal Plumbing work	100%
External plumbing work	100%
Fixing door sash	100%
Bathroom tiling	100%
Floor tiling	100%
Lift wall tile	100%
Balcony tiling	100%
Lobby tiling	100%
Staircase tiling	100%
Roof work	100%
Aluminum work	100%
Lift work – mechanical installation	100%
Electrical installation	100%
External ceiling work	100%
Terrace heat insulation & water proofing work	100%

## **PROGRESS IMAGES**

**Lot No 01**



**Lot No 2**



**Lot No 03**



**Lot No 04**



**Lot No 05**



**Internal Finishing work**





**Fully Completed Lot 04 Lift**



**Pool Changing Room**



**Pantry Cupboard in Lot 03**

